5/18

DART AEROSPACE LTD.	Work Order:	22977
Description: Saddle Fitting, Fwd (Outboard/Inboard)	Part Number:	D2571/D2572
<b>Drawing:</b> D2571 Rev. D/D2572 Rev. D	Qty:	12
		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty			
1	DC	Issue Traveller	KI	05.04.13	12			
		Dwg not required	11 ()	05.09.15	16			
2	MV	Make from D6101-007 billet for D2571						
		Ensure that grain is along 7.75" length  Batch No: 1371818	18th	05/04/15	17			
3	MV	Make from D6101-005 billet for D2572	-		<del> </del>			
3	1010	Ensure that grain is along 5.00" length		-11				
		Batch No: 13 218174	156	05/04/15	15			
4	MV	Fixturing W/O No. W/A		1				
		Fixturing Inspection last completed o Staylic by The	BC	05/04/15	N			
5	MV	Program Batch No. 22977						
		Double check by: \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	CA	05/04/1	12			
6	MV	Machine Step No 1 per Folio FA051 and inspect per attached	Vid	25.04,25	12			
7	MV	Dimension Sheets   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect per attached   CC     Machine Step No 2 per Folio FA051 and inspect	/		1			
<b>'</b>	1010	Dimension Sheets	BC.	65.04.25	12			
8	MV	Machine Step No 3 per Folio FA051 and inspect per attached	1	63 1.23				
	""	Dimension Sheets	136. I	05-04-25	12			
9	MV	Machine keyway as per dwg D2571 & D2572	1 .	1				
			a	05.04.25	12			
10	MV	Deburr and remove all machining marks	19	200	12			
44	14)/	T	u	0564.25	12			
11	MV	Tumble for 20 minutes to remove share edges # oy a 21 124	E	05.04.25	12			
12	QC1	Inspect all dimensions to dimension sheets	Be		12			
		,	le	05:04.25	12			
13	QC7	Second inspection	17/		12			
14	FP	Acid etch and alodine as per QSI 005 4.1		15.01-25	16			
14		Acid etch and alodine as per QSI 005 4.1	M	05 04 17	11.			
- 15	FP	Powder Coat High Gloss White (4.3.5.1) per QSI 005 4.3	1000					
	•	· · · · · · · · · · · · · · · · · · ·	M	BBOL	12			
16	QC3	Inspect Powder Coat	^					
			Cd	05/05/03	12			
17	ST	Identify and Stock.	4		_			
40			$-\alpha$	05/05/03	19			
18	AC	Cost / Part / 8 7 4 5 / 50 72	300	05.05.05	12			
19	DC	Cost / Part/8 7, 45 /50,72 Close W/O /75.42 /50.72	1 4					
		Inspection Level 21	1988	05.05.11	12			
n	5	Change	!	Dy Anne				

Rev	Date	Change	Revised By	Approved
G	01.04.27	Added D6101-007 & step 8	EC	
H	02.02.01	Added Inspection level 5 and Inspection Level 21	SM	$\Delta$
1	02.10.02	Re-format; Change to Dwg Rev. D & incorporated D2572	KJ 宋	, (

